AccV Rename

Backup

Summary
Cash Accounts 3
Expense Claims 0
Customers 35
Sales Quotes 1
Sales Orders 0
Sales Invoices 134
Credit Notes 0
Suppliers 27
Purchase Orders 9
Purchase Invoices 39
Employees 1
Payslips 0
Inventory Items 192
Inventory Write-offs 0
Fixed Assets 0

Sales Invoices | New Sales Invoice | Search | Search

		Invoice date	#	PO #	Customer	Description	Invoice total	Balance due	Status
Edit	View	14/06/2016	150		P&N Sales		A$ 159.50	A$ 0.00	Paid in full
Edit	View	1/06/2016	149		Feastcorp Campbelltown	Fault Given: Not heating. Disconnect machine and take to workshop. Clean all the muck out of the bottom of the machine and then fault find. The Input/output board was faulty , replace and test. Solid state relay was then found be be not switching on. Remove and replace. It was then found that water was not always going into tank, check level probe assy and find that it had corroded, replace. replace whipper shaft seals and then test whipper motors, one milk motor was not running up to speed and making bearing noise, remove and replace. Coffee auger was also found to be worn down, replace.Return machine to site and connect 3 pin plug. PLEASE NOTE ..The remaining 2 whipper motors are from 2010. AS WELL WE HAVE NOT CHARGED FOR THE FULL AMOUNT OF TECH LABOUR, WE HAVE SPENT 6.5 HOURS ON THIS MACHINE INCLUDING GIVING IT A GOOD CLEAN INSIDE	A$ 913.28	A$ 0.00	Paid in full
Edit	View	22/05/2016	148		Feastcorp Penrith	No.1 Machine. Check machine too many faults to be able to fix machine on site. Move the No.2 machine round in place and fit loan machine in its place. Then find that inlet hose from tap faulty someone had changed the hose but instead of a food grade hose they had used a washing machine hose. Run machine up in workshop and find that all the whipper motors were going, partly due to the whipper impellers being fitted incorrectly. You could see this from	A$ 979.91	A$ 0.00	Paid in full